

PowerPoint slides extracted from the paper

“ Field Investigation on Regional Sediment Movement Around Shounan Coast”, ICCE 2004, Lisbon


Hiratsuka Harbour

Sagami River


**Protected
Chigasaki Beach**



Anthropogenic impacts



Beach Erosion at Sagami river mouth



Broken road by a Typhoon

Seisho Bypassing Road was broken at Oiso, 5km east from the Sagami Rivermouth

